LLO LAN

NORMAN AKASHI President

BRUCE JUGAN Vice President

ZEKI KAYIRAN Treasurer

DAVID S. REGO Secretary

KENNETH S. BRADBURY Director KOREY S. BRADBURY General Manager

Telephone (323) 722-8654

Fax (323) 722-5529

Re: Lead Service Line Inventory

April 4, 2024

MLWC Customer,

Per the requirement of the Department of Drinking Water (DDW) and the Environmental Protective Agency (EPA), Montebello Land and Water Company (MLWC) has completed the service line inventory of the water system. This was completed by physical inspection at the water meter. After digging up the service lines upstream and downstream of the water meter, each service line type was determined. When the customers service line was not accessible in the meter box, the water service line type at the house was used.

After completing the survey of all MLWC's and its customers service lines, it was determined that MLWC and its customers do NOT have any lead service lines.

Regards,

Korey Bradbury General Manager